


Sequencing

30 cycles of 3 steps :

Step 1 : denaturation


1 minut 94 °C



Step 2 : annealing

15 seconds 50 °C


1 primer !!!!



Step 3 : extension

4 minutes 60 °C

mixture of dNTP's | and ddNTP's ↓



(Andy Vierstraete 1999)

